

CHRYSLER

DISTRIBUTORS AND PARTS

| YEAR | MODEL | DISTRIBUTOR | CONTACT SET | | CON- DENSER | CAP | ROT CR | IGNITION COIL | RESISTOR UNIT | VACUUM CONTROL | PRIMARY LEAD |
|---------|-------------------------------|-----------------------|-----------------------|-----------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| | | | POWER | VENTED | | | | | | | |
| 1951-52 | 6 Cyl. | IAT-4012 1345 464 | 1 CH-3P 2084 075 | 1 CH-3V 2421 179 | CH-101 1818 757 | CH-206 1343 576 | CH-303 1343 587 | CH-410 2421 190 | — | CH-703 1881 754 | CH-901 1343 582 |
| 1951-54 | 8 Cyl. | IAZ-4001A 1479 139 | 3,4 CH-4P 2084 077 | 3,4 CH-4V 2421 175 | " " | CH-203 1126 570 | CH-301 868 096 | " " | — | CH-733 1439 671 | CH-903 1383 958 |
| 1951-54 | 8 Cyl. | IAZ-4001B 1479 139 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | " " | " " |
| 1953-54 | 6 Cyl. | IAT-4102 1479 588 | 1 CH-3P 2084 075 | 1 CH-3V 2421 179 | " " | CH-206 1343 576 | CH-303 1343 587 | " " | — | CH-703 1881 754 | CH-905 1495 568 |
| 1953-54 | 6 Cyl. | IAT-4102 1479 588 | 1 " " | 1 " " | " " | " " | " " | " " | — | " " | " " |
| 1953-54 | 6 Cyl. | IAT-4102 1479 588 | 1 " " | 1 " " | " " | " " | " " | " " | — | " " | " " |
| 1953-54 | 8 Cyl. | IAZ-4001B 1479 139 | 3,4 CH-4P 2084 077 | 3,4 CH-4V 2421 175 | " " | CH-203 1126 570 | CH-301 868 096 | " " | — | CH-733 1439 671 | CH-903 1383 958 |
| 1953-54 | 8 Cyl. | IAZ-4001C 1540 552 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | " " | " " |
| 1955 | 8 Cyl. | IAZ-4001E 1626 661 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | " " | " " |
| 1955 | 8 Cyl. | IAZ-4001F 1641 707 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | " " | " " |
| 1955 | C-300 8 Cyl. | IAZ-4001G 1658 989 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | CH-734 1627 234 | " " |
| 1955 | C-300 8 Cyl. | IAZ-4001G 1658 989 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | — | " " | " " |
| 1956 | Windsor | IBJ-4303A 1658 869 | 3,4 " " | 3,4 " " | " " | CH-209 1658 534 | CH-306 1658 535 | CH-408 2084 847 | CH-452 2275 590 | CH-738 1689 773 | " " |
| 1956 | Windsor | IBJ-4303C 1704 260 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | CH-733 1439 671 | CH-906 1658 602 |
| 1956 | New Yorker | IBK-4301A 1642 392 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | " " | CH-903 1383 958 |
| 1956 | New Yorker | IBK-4301A 1424 392 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | " " | " " |
| 1956 | C-300 | IBK-4301C 1704 309 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | CH-737 1689 765 | " " |
| 1956 | C-300 | IBK-4301C 1704 309 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | " " | " " |
| 1957 | Windsor Early | IBP-4002A 1770 750 | 5 CH-6P 2084 078 | 5 CH-6V 2421 177 | " " | " " | " " | " " | " " | CH-706 1881 929 | CH-909 2084 865 |
| 1957 | Windsor Late | IBP-4002A 1770 750 | 5 " " | 5 " " | " " | " " | " " | " " | " " | " " | " " |
| 1957 | New Yorker Early | IBK-4304 1689 325 | 5 " " | 5 " " | " " | " " | " " | " " | " " | CH-738 1689 773 | CH-903 1383 958 |
| 1957 | New Yorker Late | IBK-4304 1689 325 | 5 " " | 5 " " | " " | " " | " " | " " | " " | " " | " " |
| 1958 | Windsor, Saratoga | IBP-4002F 1841 514 | 5 " " | 5 " " | " " | " " | " " | " " | " " | CH-700 1879 605 | CH-909 2084 865 |
| 1958 | Windsor, Saratoga | IBP-4002F 1841 514 | 5 " " | 5 " " | " " | " " | " " | " " | " " | " " | " " |
| 1958 | New Yorker | IBS-4007A 1841 515 | 3,4 CH-4P 2084 077 | 3,4 CH-4V 2421 175 | " " | " " | " " | " " | " " | CH-738 1689 773 | CH-903 1383 958 |
| 1958 | New Yorker | IBS-4007A 1841 515 | 3,4 " " | 3,4 " " | " " | " " | " " | " " | " " | " " | " " |
| 1959 | Windsor, Saratoga | IBP-4006 1842 804 | CH-9P 2084 079 | CH-9V 2421 176 | " " | " " | " " | " " | " " | CH-701 1881 748 | CH-913 2275 581 |
| 1959 | New Yorker | IBS-4010A 1842 805 | 3,7 CH-8P 2084 639 | 3,7 CH-8V 2421 173 | " " | " " | " " | " " | " " | CH-705 1881 767 | CH-903 1383 958 |
| 1960 | Windsor, Saratoga, New Yorker | IBP-4006C 1889 564 | CH-9P 2084 079 | CH-9V 2421 176 | " " | " " | " " | " " | " " | CH-714 2084 888 | CH-913 2275 581 |
| 1960 | C-300 | IBS-4011 1889 568 | 3,7 CH-8P 2084 639 | 3,7 CH-8V 2421 173 | " " | " " | " " | " " | " " | CH-713 2084 868 | CH-903 1383 958 |

1 Can Also Use CH-3/1343 581 Standard Two Piece Set

2 Two Contact Sets Required

4 Can Also Use 1658 604 Standard Two Piece Set

5 Can Also Use CH-6/1818 568 Standard Two Piece Set

7 Can Also Use Part No. CH-8/1843 339 Two Piece Set
(2 Per Box)

CHRYSLER

DISTRIBUTORS AND PARTS

| YEAR | MODEL | DISTRIBUTOR | CONTACT SET | | CON-DENSER | CAP | ROTOR | IGNITION COIL | RESISTOR UNIT | VACUUM CONTROL | PRIMARY LEAD |
|------|--|-----------------------|-----------------------|-----------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|--------------------|
| | | | POWER | VENTED | | | | | | | |
| 1961 | Windsor, Newport | IBP-4005E 2095 679 | CH-9P 2084 079 | CH-9V 2421 176 | CH-101 1818 757 | CH-209 1658 534 | CH-306 1658 535 | CH-408 2084 847 | CH-452 2275 590 | CH-729 2275 226 | CH-913 2275 581 |
| 1961 | Windsor, Newport | IBP-4005E 2095 679 | " | " | " | " | " | " | " | " | " |
| 1962 | 1-2 BBL. Carb. | 2095 836 | — | CH-15V 2098 244 | CH-103 2098 058 | CH-211 1838 514 | CH-308 1838 516 | " | " | CH-722 2098 192 | CH-911 2095 873 |
| 1962 | 2 and 4 BBL. Carb. | 2098 495 | 3.7 CH-8P 2084 639 | 3.7 CH-8V 2421 173 | CH-101 1818 757 | CH-209 1658 534 | CH-306 1658 535 | " | " | CH-713 2084 868 | CH-903 1383 958 |
| 1962 | 1-4 BBL. Carb. | 2095 987 | — | CH-15V 2098 244 | CH-103 2098 058 | CH-211 1838 514 | CH-308 1838 516 | " | " | CH-723 2098 197 | CH-911 2095 873 |
| 1963 | 361, 383 Eng. | 2095 836 | — | " | " | " | " | " | " | CH-722 2098 192 | " |
| 1963 | Pwr. Pack | 2098 495 | 3.7 CH-8P 2084 639 | 3.7 CH-8V 2421 173 | CH-101 1818 757 | CH-209 1658 534 | CH-306 1658 535 | " | " | CH-713 2084 868 | CH-903 1383 958 |
| 1963 | C-300 | 2098 726 | 3.7 " | 3.7 " | " | " | " | " | " | " | " |
| 1963 | 413 Eng. | 2098 689 | — | CH-15V 2098 244 | CH-103 2098 058 | CH-211 1838 514 | CH-308 1838 516 | " | " | CH-728 2098 734 | CH-911 2095 873 |
| 1964 | Newport (Police) C300 W/Pwr. Pack, C300K W/O Ram. Manifold, W/4 BBL. Carb. | IBS-4011C 2444 361 | 3.7 CH-8P 2084 639 | 3.7 CH-8V 2421 173 | CH-101 1818 757 | CH-209 1658 534 | CH-306 1658 535 | CH-412 2495 531 | " | CH-713 2084 868 | CH-919 2525 639 |
| 1964 | Newport (Police) C300 W/Pwr. Pack, C300K W/O Ram. Manifold W/4 BBL. Carb. | IBS-4011C 2444 361 | 3.7 " | 3.7 " | " | " | " | " | " | " | " |
| 1964 | Newport, C300 W/2 BBL. Carb. | 2444 261 | — | CH-15V 2098 244 | CH-103 2098 058 | CH-211 1838 514 | CH-308 1838 516 | " | " | CH-722 2098 192 | CH-918 2444 282 |
| 1964 | Newport, C300 W/2 BBL. Carb. | 2444 261 | — | " | " | " | " | " | " | " | " |
| 1964 | C300K W/Ram. Manifold W/2-4 BBL. Carbs. | IBS-4011D 2444 364 | 3.7 CH-8P 2084 639 | 3.7 CH-8V 2421 173 | CH-101 1818 757 | CH-209 1658 534 | CH-306 1658 535 | " | " | CH-713 2084 868 | CH-919 2525 639 |
| 1964 | C300K W/Ram. Manifold W/2-4 BBL. Carbs. | IBS-4011D 2444 364 | 3.7 " | 3.7 " | " | " | " | " | " | " | " |
| 1964 | New Yorker W/4 BBL. Carb. | 2444 263 | — | CH-15V 2098 244 | CH-103 2098 058 | CH-211 1838 514 | CH-308 1838 516 | " | " | CH-728 2098 734 | CH-918 2444 282 |
| 1964 | New Yorker W/4 BBL. Carb. | 2444 263 | — | " | " | " | " | " | " | " | " |
| 1965 | W/383 Eng. | 2444 676 | — | " | " | CH-216 2444 507 | " | " | " | CH-745 2444 677 | " |
| 1965 | W/383 Eng. | 2444 676 | — | " | " | " | " | " | " | " | " |
| 1965 | W/413 Eng. | IBS-4006K 2444 683 | 3.7 CH-8P 2084 639 | 3.7 CH-8V 2421 173 | CH-101 1818 757 | CH-218 2585 000 | CH-306 1658 535 | " | " | CH-713 2084 868 | CH-919 2525 639 |
| 1965 | W/413 Eng. | IBS-4006K 2444 683 | 3.7 " | 3.7 " | " | " | " | " | " | " | " |